

Toyota Corolla 2024

This report is **0 Days** old. For the latest report, Get It Inspected again.


OVERALL RATING

4.8
/10

Car Details

Customer/Dealer Name Hammad Paracha	Engine Capacity 1.6L - 2.0L	Mileage 345345 km	Transmission Type Automatic
Inspection Date May 23, 2026	Chassis No N/A	Engine No N/A	Registration No N/A
Fuel Type Petrol	Color N/A	Location house 76b	Registered City Richmond

★ Summary





Inspector Comments
asdhasd adsasdsa dsa da

Exterior Condition

Move your mouse over colored markers to see defect details.

* Move your mouse over colored markers to see defect details. Show Minor Scratches / Dents





Legend

- P **P**
Paint marked
- A1 **A1**
Small Scratch
- A2 **A2**
Scratch
- A3 **A3**
Big Scratch
- B1 **B1**
Small dent with scratch (size like a thumb)
- B2 **B2**
Dent with scratch (size like flat of the hand)
- B3 **B3**
Big Dent with scratch (size like elbow)
- S1 **S1**
Rust
- U1 **U1**
Small Dent
- Y1 **Y1**
Small Hole or Crack

P, Roof: painted
B3, Rear Right Fender: sada
B3, Front Bumper: dasad

Body Frame Accident Checklist (5.0/10)

50%

- ✓ Radiator Core Support
OK
- ✓ Right Strut Tower Apron
OK
- ✓ Left Strut Tower Apron
NOT OK
- ✓ Right Front Rail
OK
- ⚠ Left Front Rail
REPAIRED
- ✓ Boot Floor
NOT OK
- ✓ Boot Lock Pillar
NOT OK
- ⚠ Rear Sub Frame
REPAIRED
- ✗ Front Sub Frame
DAMAGE FOUND

Engine / Transmission / Clutch (5.0/10)

50%

- ✓ Clutch
TRANSMISSION MOUNTS OK
NOT PRESENT

Suspension / Steering (5.0/10)

50%

Interior (4.0/10)

40%

Equipment

AC / Heater (3.0/10)

30%

Electrical & Electronics (7.0/10)

70%

Exterior & Body (5.0/10)

50%

Tyres (6.0/10)

60%










Test Drive

INSPECTOR'S TEST DRIVE NOTES

"adfsasdadadada"


General Car Photos

Visual documentation of the vehicle inspection






Front Interior




Trunk Open




Tool kit/Spare tyre




Rear Interior



4 Way Switch



Key/Remote



Tyre

Disclaimer

In case of any query or concern regarding inspection please contact us. This report is based on the condition of the vehicle on the date of certification and provides an approximate estimate of the condition on that date. Except where indicated, the parts were in working condition - this report does not take into account the condition of parts not visible or not inspected. YabuhAutoMarket has relied on the odometer reading for kms driven as seen at the time of inspection and is not responsible for verifying its genuineness. The report is in no way a commitment on the condition of the car. All reports are subjective and YabuhAutoMarket and its associates cannot be held liable in any way due to the use of this report. Liability if any cannot exceed the amount paid for the inspection service therein.